

1973 Triumph TR6

Mfgr Date:  
May 1973

## Ignition Switch Replacement (Modified)

4 poles: 1, 2, 3, 4 Single Pole  
Position 4 Double Pole  
Position 3 No Pole (Blank)

